


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 24585	Main Street: REA_CROFT_DR	Cross Street: REA_RD	Location: SW
ADA ID: 05F673B112DA	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 0	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
	Possible Solutions:		Compliance			Description			Data	Compliance			Description			Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)			65.0			Yes	Ramp Slope (%)			6.4		
			Yes	Ramp Width (in)			48.0			Yes	Ramp XSlope (%)			1.5		
			N/A	Flare Type LT			Sloped			N/A	Flare Type RT			N/A		
			N/A	Flare Slope LT (%)			2.1			Yes	Flare Slope RT (%)			9.8		
			N/A	Flare Traversable LT?			Yes			N/A	Flare Traversable RT?			Yes		
			Yes	Landing Length (in)			74.0			Yes	DWS Provided?			Yes		
			Yes	Landing Width (in)			48.0			Yes	DWS Contrast?			Yes		
			Yes	Landing Slope (%)			0.7			Yes	DWS Length (in)			24.0		
			Yes	Landing X Slope (%)			1.0			Yes	DWS Full Width?			Yes		
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)			No			Yes	DWS Offset (in)			1.0		
			N/A	Shared Landing?			No									
PROW/ADA:		Not Found	Yes	Gutter Ponding?			No			Yes	Gutter Slope (%)			0.4		
			Yes	Gutter Lip Ht (in)			0.0			Yes	Gutter X Slope (%)			2.0		
			N/A	Painted X Walk1?			No			N/A	Painted X Walk2?			N/A		
				X Walk 1 Direction			To E				X Walk 2 Direction			N/A		
			N/A	X Walk 1 Width (in)			N/A			N/A	X Walk 2 Width (in)			N/A		
				X Walk 1 Slope (%)			2.8				X Walk 2 Slope (%)			N/A		
				X Walk 1 X Slope (%)			2.3				X Walk 2 X Slope (%)			N/A		
Street 1 Name		REA RD	N/A	Ramp inside XWalk1?			N/A			N/A	Ramp inside XWalk2?			N/A		
Stop Condition-Street 2		None		Road Slope (%)			N/A			N/A	Clear Space?			Yes		
Street 2 Name		N/A		Road X Slope (%)			N/A			N/A	Clear Space to XWalk (in)			N/A		
Stop Condition-Street 1		N/A	Yes	Any Obstructions?			No			Yes	Storm Grate/Utility Hazard?			No		
				Obstruction Type							Storm Grate/Utility Type					
										N/A				N/A		
										Yes	Surface Condition? (G/P)			Good		
Total Cost:		\$ 1850.00														

