

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2801 Main Street: BELL'S MILL DR **Cross Street: DUNOON LN** Location: W Initial Pass/Fail: Fail **Overall Compliance: No** 10 ADA ID: 0608F57368EE Ramp Type: Perp **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



BELL'S MILL DR Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

Total Cost: 1850.00

Compliance Description <u>Data</u> Compliance Description Data Yes Ramp Slope (%) N/A Ramp Length (in) 48.0 5.5 Yes Ramp XSlope (%) No Ramp Width (in) 36.0 2.3 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** Landing Length (in) N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) N/A DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To E X Walk 2 Direction N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) X Walk 2 Slope (%) N/A 5.4 X Walk 1 X Slope (%) 3.2 X Walk 2 X Slope (%) N/A N/A N/A N/A Ramp inside XWalk1? Ramp inside XWalk2? N/A Road Slope (%) N/A N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A

Yes

Surface Condition? (G/P)

Good





