


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                          |                         |                        |
|------------------------|--------------------------|-------------------------|------------------------|
| Intersection ID: 11642 | Main Street: N_POPLAR_ST | Cross Street: W_9TH_ST  | Location: E            |
| ADA ID: 0638E78A11C2   | Ramp Type: PerpDiag      | Initial Pass/Fail: Fail | Overall Compliance: No |
|                        |                          |                         | Severity Score: 13.75  |

| Codes/Mitigation Info/Possible Solution                                                    |                                                                                     |  | Field Measurements/Component Compliance |                          |             |
|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--|-----------------------------------------|--------------------------|-------------|
|            | Possible Solutions:                                                                 |  | <b>Compliance</b>                       | <b>Description</b>       | <b>Data</b> |
|                                                                                            | <b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b> |  | N/A                                     | Ramp Length (in)         | 64.0        |
|                                                                                            |                                                                                     |  | Yes                                     | Ramp Width (in)          | 48.0        |
|                                                                                            |                                                                                     |  | N/A                                     | Flare Type LT            | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Flare Slope LT (%)       | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Flare Traversable LT?    | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Landing Length (in)      | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Landing Width (in)       | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Landing Slope (%)        | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Landing X Slope (%)      | N/A         |
| <p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>R304.2.2, R304.5.3</b></p> |                                                                                     |  | N/A                                     | Flare Type RT            | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Flare Slope RT (%)       | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Flare Traversable RT?    | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | DWS Provided?            | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | DWS Contrast?            | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | DWS Length (in)          | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | DWS Full Width?          | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | DWS Offset (in)          | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Gutter Ponding?          | N/A         |
|                                                                                            |                                                                                     |  | N/A                                     | Gutter Lip Ht (in)       | N/A         |
| <p>Total Cost:</p> <p><b>\$ 3200.00</b></p>                                                |                                                                                     |  | N/A                                     | Painted X Walk1?         | No          |
|                                                                                            |                                                                                     |  |                                         | X Walk 1 Direction       | To NW       |
|                                                                                            |                                                                                     |  | N/A                                     | X Walk 1 Width (in)      | N/A         |
|                                                                                            |                                                                                     |  |                                         | X Walk 1 Slope (%)       | 4.5         |
|                                                                                            |                                                                                     |  |                                         | X Walk 1 X Slope (%)     | 2.0         |
|                                                                                            |                                                                                     |  | N/A                                     | Ramp inside XWalk1?      | N/A         |
|                                                                                            |                                                                                     |  |                                         | Road Slope (%)           | 1.7         |
|                                                                                            |                                                                                     |  |                                         | Road X Slope (%)         | 5.0         |
|                                                                                            |                                                                                     |  | N/A                                     | Any Obstructions?        | N/A         |
|                                                                                            |                                                                                     |  |                                         | Obstruction Type         |             |
|                                                                                            |                                                                                     |  | N/A                                     |                          | N/A         |
|                                                                                            |                                                                                     |  | Yes                                     | Surface Condition? (G/P) | Good        |

