

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10040584Main Street: W\_ARROWOOD\_RDCross Street: N/ALocation:NWADA ID: 064AA6A86496Ramp Type: PerpInitial Pass/Fail: PassOverall Compliance: NoSeverity Score:0

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



THE RESERVE OF THE PARTY OF THE	A PART OF THE PART
Street 1 Name	W ARROWOOD RD
Stop Condition-Street 2	2 None
Street 2 Name	N/A
Stop Condition-Street	1 <b>N/A</b>

Possible Solutions:					
Remove & Replace Entire Ramp.					
Surveyor Notes:					
N/A					
PDOW/ADA					
PROW/ADA:					
R304.2.1, R304.2.2-Perp, R304.3.2- Para, R304.5.3, R305.2					
1 414, 11004.0.0, 11000.2					



Total Cost:



1850.00

Field Measurements/Component Compilance								
Compl	iance Description	Data	Comp	liance Description	Data			
N/A	Ramp Length (in)	30.5	Yes	Ramp Slope (%)	8.0			
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.4			
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	5.0	Yes	Flare Slope RT (%)	2.4			
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	Yes			
No	Landing Length (in)	26.0	Yes	DWS Provided?	Yes			
Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes			
No	Landing Slope (%)	4.3	Yes	DWS Length (in)	24.0			
No	Landing X Slope (%)	3.3	Yes	DWS Full Width?	Yes			
N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.0			
N/A	Shared Landing?	No						
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.0			
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.6			
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	5.0		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	Yes			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			