

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025558 Main Street: E W T HARRIS BV **Cross Street: N/A** Location: NW ADA ID: 06658987AA2A Ramp Type: ParaDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



EWTHARRISBV Street 1 Name Stop Condition-Street 1 None Street 2 Name **ENTRANCE** Stop Condition-Street 2 StopSign Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

N/A

PROW/ADA:

R304.3.2, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compilance					
Compliance Description		Data	Compliance Description		Data
N/A	Ramp Length LT (in)	56.0	N/A	Ramp Length RT (in)	48.0
Yes	Ramp Width LT (in)	82.0	Yes	Ramp Width RT (in)	83.0
No	Ramp Slope LT (%)	12.7	No	Ramp Slope RT (%)	10.0
No	Ramp XSlope LT (%)	3.6	Yes	Ramp XSlope RT (%)	1.9
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To E		X Walk 2 Direction	To S
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	2.6
	X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	1.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.8	N/A	Clear Space?	N/A
	Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	5.2
		,	•	,	





