

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | Main Ofr | | 0 | 04 | | | | Landland | 05 | |
|--|--------------------------|-----------------------------|---------|--|-----------------------|------|--------------------|-----------------------------|-------|--|
| Intersection ID: 17633 | Main Street: NORMANDY_RD | | | Cross Street: ROSWELL_AV | | | | Location: | SE | |
| ADA ID: 068027C98BC5 Ramp Type: Directional1 | | | Initial | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 26.25 | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | - 300000 | Possible Solutions: | | Compliance Description Data Complian | | | liance Description | Data | | |
| | 10458348 | Remove & Replace Entire Ram | p. | N/A | Ramp Length (in) | 64.5 | N/A | Grade Break? | N/A | |
| | | | • | Yes | Ramp Width (in) | 53.0 | N/A | Grade Break Slope (%) | 0.0 | |
| | | | | No | Ramp Slope (%) | 14.7 | N/A | Grade Break XSlope (%) | 0.0 | |
| | R. 2 a. 3. | | | No | Ramp XSlope (%) | 3.4 | | | | |
| A REAL AND | and Paris | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| a b | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 | |
| NOP | | Surveyor Notes: | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | MANDY RD | N/A | | N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A | |
| | 2222 | | | N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A | |
| | | | | N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A | |
| | | | | N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A | |
| Part I fame . | Part 1 | PROW/ADA: | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A | |
| | the last | R304.2.2, R304.5.3 | | N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A | |
| | | | N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A | | |
| | | | | N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A | |
| | 101 18 | | | N/A | Painted X Walk1? | No | | Road Slope (%) | 0.8 | |
| Street 1 Name | NORMANDY RD | | | | X Walk 1 Direction | To N | | Road X Slope (%) | 5.7 | |
| Stop Condition-Street 1 | StopSign | | | | X Walk 1 Width (in) | N/A | | Clear Space? | N/A | |
| Street 2 Name | N/A | | | | X Walk 1 Slope (%) | 0.8 | N/A | Clear Space to XWalk (in) | N/A | |
| Stop Condition-Street 2 | N/A | | | | X Walk 1 X Slope (%) | 5.7 | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | | | N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | | |
| | | | | N/A | Any Obstructions? | N/A | | | N/A | |
| | | Total Cost: \$ | 1600.00 | | Obstruction Type | | Yes | Surface Condition? (G/P) | Good | |
| | | | | | | N/A | N/A | Curb Slope (%) | 13.6 | |

