cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9611	tersection ID: 9611 Main Street: COVECREEK_DR			Cross	Street:	THE_PLAZA	Location:	NE		
ADA ID: 069B008CF4AD	069B008CF4AD Ramp Type: PerpDiag			Initial	Pass/Fa	ail: Fail Overall (o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
Charles and the		Possible Solutions:			Compliance Description			Data Compliance Description		
A AND SI		Remove & Replace Curb Ra Two New Directional Ramps Equivalent.	Ram	o With	N/A	Ramp Length (in)	58.0	No	Ramp Slope (%)	8.9
and the second			•		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.1
			•		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A MARKEN STATE	2 4 1				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	A CARLER	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
B. Tark	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A		ζ, γ		
5	The second se	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R30			04.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			•		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
T The Mark	A MARINE MARINE					X Walk 1 Direction	To W		X Walk 2 Direction	To S
					N/A	X Walk 1 Width (in)	96.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	COVE CREEK DR	-				X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	3.1
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	3.7		X Walk 2 X Slope (%)	0.5
Street 2 Name	THE PLAZA				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None					Road Slope (%)	1.8	N/A	Clear Space?	N/A
						Road X Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

