

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 2983Main Street: YELLOW_ROSE_LNCross Street: BROWNE_RDLocation:NWADA ID: 06B7459746D0Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name

YELLOW ROSE LN

Stop Condition-Street 2

StopSign

Street 2 Name

N/A

Stop Condition-Street 1

N/A

| POSSIBLE SOLUTION | | | |
|-------------------------------|-----|--|--|
| Possible Solutions: | Co | | |
| Remove & Replace Entire Ramp. | N/A | | |
| Restripe Crosswalk. | | | |
| | N/A | | |
| Surveyor Notes: | N/A | | |
| N/A | N/A | | |
| | N/ | | |
| | N/A | | |
| | N/A | | |
| PROW/ADA: | N/A | | |
| R304.5.1, R304.2.2, R304.5.3 | N/A | | |
| | N/A | | |
| | N/A | | |
| | N// | | |





Total Cost:



2050.00

| Field Measurements/Component Compliance | | | | | | |
|---|-----------------------------|-------|------|-----------------------------|------|--|
| Comp | Compliance Description Data | | Comp | liance Description | Data | |
| N/A | Ramp Length (in) | 57.0 | No | Ramp Slope (%) | 9.8 | |
| No | Ramp Width (in) | 44.5 | No | Ramp XSlope (%) | 2.8 | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| N/A | Shared Landing? | N/A | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A | |
| | X Walk 1 Direction | To S | | X Walk 2 Direction | N/A | |
| N/A | X Walk 1 Width (in) | 120.0 | N/A | X Walk 2 Width (in) | N/A | |
| | X Walk 1 Slope (%) | 1.5 | | X Walk 2 Slope (%) | N/A | |
| | X Walk 1 X Slope (%) | 0.0 | | X Walk 2 X Slope (%) | N/A | |
| N/A | Ramp inside XWalk1? | No | N/A | Ramp inside XWalk2? | N/A | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | N/A | | | N/A | |
| | | | Yes | Surface Condition? (G/P) | Good | |