

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19240Main Street:GRIFFITH\_RDCross Street:WESTPARK\_DRLocation:NEADA ID: 06C570259319Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WESTPARK DR None GRIFFITH RD StopSign

Possible Solution
Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.
Surveyor Notes:
N/A
PROW/ADA:
R304.2.2

Total Cost: \$ 3200.00

rield Measurements/Component Compilance						
Compliance Description D			Comp	liance Description	Data	
N/A	Ramp Length (in)	112.0	No	Ramp Slope (%)	13.2	
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.2	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	0.4	
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	0.3	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	1.1	N/A	Clear Space?	N/A	
	Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	

Yes

Surface Condition? (G/P)

Good





