


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 13202	Main Street: KILBORNE_DR	Cross Street: N/A	Location: NW
ADA ID: 06E080A52DD0	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance						
	Possible Solutions:	Compliance		Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	8.6	
		No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	1.0	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
Surveyor Notes:	N/A	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A		Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
PROW/ADA:	Not Found, R304.5.1, R304.2.2	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A	N/A	Gutter Slope (%)	N/A	
		N/A	Gutter Ponding?	N/A				
		N/A	Gutter Lip Ht (in)	N/A				
Total Cost:	\$ 3200.00	N/A	Painted X Walk1?	No				N/A
			X Walk 1 Direction	To S		X Walk 2 Direction	To E	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	3.1	
			X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	3.2	
N/A	N/A	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	2.5	N/A	Clear Space?	N/A	
			Road X Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
			Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	
				Yes	Surface Condition? (G/P)	Good		

