

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.1

4.1

Intersection ID: 48460 Main Street: TARPWAY_RD **Cross Street: PANGLEMONT DR** Location: W **Overall Compliance: No** ADA ID: 06E32E038A38 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

47.0 No

Yes

48.5

Data Compliance Description

Ramp Slope (%)

Ramp XSlope (%)



Possible Solutions:	Compliance Description
Remove & Replace Entire Ramp.	N/A Ramp Length (in)
·	No Ramp Width (in)
	N/A Flare Type LT
	N/A Flare Slope LT (%)
	N/A Flare Traversable L
	N/A Landing Length (in)
Surveyor Notes:	N/A Landing Width (in)
N/A	N/A Landing Slope (%)
	N/A Landing X Slope (%
	N/A Landing Curb? (Y/N
	N/A Shared Landing?
PROW/ADA:	N/A Gutter Ponding?
Not Found, R304.5.1, R304.5.3	N/A Gutter Lip Ht (in)
	N/A Painted X Walk1?
	X Walk 1 Direction
	N/A X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (
	N/A Ramp inside XWalk

1		
	>	



THE RESERVE OF THE PROPERTY OF							. ,			,		
						N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	接口是是					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
						N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
E CONTRACTOR OF THE SECOND OF						N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	PANGLEMOND	Surveyor Notes:				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
<mark>⊌</mark>	- THENT DR	N/A				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
						N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	4 4					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
通過學科技術研究	A PAR	í				N/A	Shared Landing?	N/A				
6 1		PROW/ADA:				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Both I	Not Found,	R304.5.1, R304.	.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
100000000000000000000000000000000000000		ĺ	•			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	AUGUST AND THE						X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
	THE PERSON NAMED IN					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	TARPWAY RD						X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None						X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A					N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A						Road Slope (%)	N/A	N/A	Clear Space?	N/A	
							Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
						N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
								N/A			N/A	
									Yes	Surface Condition? (G/P)	Good	
		Service of Service Park										
				THE PARTY OF	Charles .							