

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27865Main Street: ALEXANDER_MILL_DRCross Street: MCCOMB_MANOR_CTLocation:SWADA ID: 07085B7D8A05Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:25

Codes/Mitigation Info/Possible Solution



Street 1 Name
ALEXANDER MILL DR
Stop Condition-Street 2
None
Street 2 Name
N/A
Stop Condition-Street 1
N/A

"	1 033ibic Odiation	
1	Possible Solutions:	<u>c</u>
1	Remove & Replace Entire Ramp.	N
3		Υ
		N
		N
ú		N
Š		N
2	Surveyor Notes:	N
Ž	N/A	N
8		N
`		N
		N
	PROW/ADA:	N
1	Not Found, R304.2.2, R304.5.3	N
ļ		N
Š		
æ		N
		N

	BASE SEE
	A STATE OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON



Total Cost:



1850.00

Field Measurements/Component Compliance									
Compliance Description		Data	Comp	oliance	Description	Data			
N/A	Ramp Length (in)	52.0	No	Ramp	Slope (%)	9.1			
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	5.9			
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A			
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter	X Slope (%)	N/A			
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A			
	X Walk 1 Direction	To N		X Wal	k 2 Direction	N/A			
N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	N/A			
	X Walk 1 Slope (%)	4.4		X Wal	k 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	3.4		X Wal	k 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm	Grate/Utility Type				
		N/A				N/A			
			Yes	Surfac	ce Condition? (G/P)	Good			