


Intersection ID: 12605		Main Street: KENSINGTON_DR		Cross Street: THE_PLAZA		Location:		NW							
ADA ID: 0727E00F8C03		Ramp Type: Perp		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5							
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance											
		Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data	
		Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		84.0		No		Ramp Slope (%)		9.0	
				Yes		Ramp Width (in)		56.0		Yes		Ramp XSlope (%)		1.8	
				N/A		Flare Type LT		N/A		N/A		Flare Type RT		N/A	
				N/A		Flare Slope LT (%)		N/A		N/A		Flare Slope RT (%)		N/A	
				N/A		Flare Traversable LT?		N/A		N/A		Flare Traversable RT?		N/A	
				N/A		Landing Length (in)		N/A		N/A		DWS Provided?		N/A	
				N/A		Landing Width (in)		N/A		N/A		DWS Contrast?		N/A	
				N/A		Landing Slope (%)		N/A		N/A		DWS Length (in)		N/A	
				N/A		Landing X Slope (%)		N/A		N/A		DWS Full Width?		N/A	
<div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>R304.2.2</div>		N/A		N/A		Landing Curb? (Y/N)		N/A		N/A		DWS Offset (in)		N/A	
				N/A		Shared Landing?		N/A							
				N/A		Gutter Ponding?		Yes		N/A		Gutter Slope (%)		N/A	
				N/A		Gutter Lip Ht (in)		N/A		N/A		Gutter X Slope (%)		N/A	
				N/A		Painted X Walk1?		No		N/A		Painted X Walk2?		N/A	
						X Walk 1 Direction		To S				X Walk 2 Direction		N/A	
				N/A		X Walk 1 Width (in)		N/A		N/A		X Walk 2 Width (in)		N/A	
						X Walk 1 Slope (%)		2.2				X Walk 2 Slope (%)		N/A	
						X Walk 1 X Slope (%)		2.1				X Walk 2 X Slope (%)		N/A	
				N/A		Ramp inside XWalk1?		N/A		N/A		Ramp inside XWalk2?		N/A	
<div>Total Cost:</div> <div>\$ 1850.00</div>						Road Slope (%)		N/A		N/A		Clear Space?		N/A	
						Road X Slope (%)		N/A		N/A		Clear Space to XWalk (in)		N/A	
				N/A		Any Obstructions?		N/A		N/A		Storm Grate/Utility Hazard?		N/A	
						Obstruction Type						Storm Grate/Utility Type			
								N/A						N/A	
								Yes		Surface Condition? (G/P)		Good			

