

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 19009	Main Street: BRACE_RD	Cross Street: BRAEBURN_RD	Location: SW
ADA ID: 0746FD6397D0	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 10.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A	Ramp Length (in)	84.0	Yes	Ramp Slope (%)	5.2
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.9
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	0.8	Yes	Flare Slope RT (%)	3.8
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
			No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
			No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
			No	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
			No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
Surveyor Notes:		N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.0	
PROW/ADA:		N/A	Shared Landing?	N/A				
Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305.2			Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	5.0
			Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	4.9
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	7.1
				X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	1.1
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	3.5	N/A	Clear Space?	Yes
				Road X Slope (%)	6.6	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good

