


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 13246	Main Street: CENTRAL_AV	Cross Street: TIPPAH_PARK_CT	Location: NE
ADA ID: 0752B12C0E0C	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		<b>Yes</b>	Ramp Length (in)	27.0
			<b>No</b>	Ramp Width (in)	47.5
			<b>N/A</b>	Flare Type LT	N/A
			<b>N/A</b>	Flare Slope LT (%)	N/A
			<b>N/A</b>	Flare Traversable LT?	N/A
			<b>N/A</b>	Landing Length (in)	N/A
			<b>N/A</b>	Landing Width (in)	N/A
			<b>N/A</b>	Landing Slope (%)	N/A
			<b>N/A</b>	Landing X Slope (%)	N/A
			<b>N/A</b>	Landing Curb? (Y/N)	N/A
			<b>N/A</b>	Shared Landing?	N/A
			<b>N/A</b>	Gutter Ponding?	N/A
			<b>N/A</b>	Gutter Lip Ht (in)	N/A
			<b>No</b>	Painted X Walk1?	N/A
				X Walk 1 Direction	To W
			<b>N/A</b>	X Walk 1 Width (in)	N/A
				X Walk 1 Slope (%)	1.0
				X Walk 1 X Slope (%)	3.0
			<b>N/A</b>	Ramp inside XWalk1?	N/A
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.5.1</b></p>			<b>N/A</b>	Ramp inside XWalk2?	N/A
				Road Slope (%)	2.0
				Road X Slope (%)	3.2
			<b>N/A</b>	Any Obstructions?	N/A
				Obstruction Type	
			<b>N/A</b>		N/A
			<b>Yes</b>	Surface Condition? (G/P)	Good

Street 1 Name	TIPPAH PARK CT
Stop Condition-Street 2	StopSign
Street 2 Name	CENTRAL AV
Stop Condition-Street 1	None

Total Cost: \$ 3200.00

