

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.8

0.5

N/A

Intersection ID: 20286 Main Street: LONGDALE DR **Cross Street: S TRYON ST** Location: SE Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5 ADA ID: 07640DF6AA63 Ramp Type: Perp

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

<u>Data</u>



LONGDALE DR Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A

Compliance Description Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.2.2

N/A 1850.00

Ramp Length (in) No N/A 81.0 Ramp Slope (%) Ramp XSlope (%) Yes Ramp Width (in) 48.0 Yes N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A Landing Slope (%) DWS Length (in) Landing X Slope (%) N/A N/A DWS Full Width? Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? **Gutter Ponding?** N/A N/A Gutter Slope (%) Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To N X Walk 2 Direction N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) X Walk 2 Slope (%) 6.0 X Walk 2 X Slope (%) X Walk 1 X Slope (%) 0.6 N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) N/A N/A Clear Space? Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A Any Obstructions? N/A Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good





Total Cost:

