

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10100	Main Street: ASHLEY_RD			Cross Street: FREEDOM_DR			Location: E		
ADA ID: 076CBA0D6D44	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score: 8.75		8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						liance Description	Data
Monument 1	-	Remove & Replace Entire Ram	0.	N/A	Ramp Length (in)	48.5		Ramp Slope (%)	6.9
			-	No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	2.0
	1 50			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1 Belly			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A B A B	4			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A JUNE I	inder i	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
SHE CONTRACTOR	me Com	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
VE DANKI	1. 8			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	(1) plan			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
S BI	RUN			N/A	Shared Landing?	N/A			
Burk B		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
S P P B		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	4.			N/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	REEDOM DR	-			X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	3.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

