

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 18274	Main Street: FERNCLIFF_RD	Cross Street: KNOLLWOOD_RD	Location: E
ADA ID: 0799DE68FC1B	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	
Severity Score: 2.75			

	Possible Solutions:		Compliance		Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A	Ramp Length (in)	26.0	Yes	Ramp Slope (%)	8.0	
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.8	
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	10.3	Yes	Flare Slope RT (%)	6.3	
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
			Yes	Landing Length (in)	57.0	Yes	DWS Provided?	Yes	
			Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
			No	Landing Slope (%)	3.4	Yes	DWS Length (in)	24.5	
			No	Landing X Slope (%)	2.7	Yes	DWS Full Width?	Yes	
Surveyor Notes: N/A 									

