


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 3352	Main Street: DAVIS_RIDGE_DR	Cross Street: FALLS_RIDGE_LN	Location: NE
ADA ID: 07C6BC8DDF2F	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 1.25	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance			
	Possible Solutions:	Compliance	Description	Data	Compliance
	Remove & Replace Entire Ramp.	Yes	Ramp Length (in)	48.5	Yes
		Yes	Ramp Width (in)	48.0	Yes
		N/A	Flare Type LT	N/A	N/A
		N/A	Flare Slope LT (%)	N/A	N/A
		N/A	Flare Traversable LT?	N/A	N/A
		N/A	Landing Length (in)	N/A	N/A
		N/A	Landing Width (in)	N/A	N/A
		N/A	Landing Slope (%)	N/A	N/A
		N/A	Landing X Slope (%)	N/A	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found</p>		N/A	Flare Type RT	N/A	N/A
		N/A	Flare Slope RT (%)	N/A	N/A
		N/A	Flare Traversable RT?	N/A	N/A
		N/A	DWS Provided?	N/A	N/A
		N/A	DWS Contrast?	N/A	N/A
		N/A	DWS Length (in)	N/A	N/A
		N/A	DWS Full Width?	N/A	N/A
		N/A	DWS Offset (in)	N/A	N/A
		N/A	Shared Landing?	N/A	N/A
		N/A	Gutter Ponding?	N/A	N/A
		N/A	Gutter Lip Ht (in)	N/A	N/A
		N/A	Painted X Walk1?	No	N/A
			X Walk 1 Direction	To S	
		N/A	X Walk 1 Width (in)	N/A	N/A
			X Walk 1 Slope (%)	3.1	
			X Walk 1 X Slope (%)	5.9	
		N/A	Ramp inside XWalk1?	N/A	N/A
			Road Slope (%)	N/A	
			Road X Slope (%)	N/A	
		N/A	Any Obstructions?	N/A	N/A
Total Cost:		\$	1850.00		
			Obstruction Type		
				N/A	N/A
				Yes	Surface Condition? (G/P)
					Good

