

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/AMain Street:STEEL\_CREEK\_RDCross Street:ENTRANCE\_DRLocation:WADA ID: 07F8754C6D37Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

STEELE CREEK RD None ENTRANCE DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance					
Compliance Description		Data	Comp	liance Description	Data
N/	A Ramp Length (in)	96.0	Yes	Ramp Slope (%)	8.0
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	2.9
N/	A Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/	A Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/	A Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/	A Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/	A Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/	A Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/	A Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/	A Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/	A Shared Landing?	N/A			
N/	A Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/	A Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/	A Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To E		X Walk 2 Direction	To N
N/	A X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	2.0
	X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	1.0
N/	A Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	3.4	N/A	Clear Space?	N/A
	Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
N/	A Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





