

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28609Main Street:FOX_THORNE_DRCross Street:TROTTER_RDLocation:NWADA ID: 0800CA4BAD8ERamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:17.5

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance



Street 1 Name	FOX THORNE DR
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

T COCIDIO COIGNION	
Possible Solutions:	Co
Remove & Replace Entire Ramp.	N/A
·	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
Not Found, R304.5.1	N/A
	N/A
	N/A
	N/A

Age .	1



1850.00

Compli	ance Description	Data	Compli	ance	Description	Data
N/A	Ramp Length (in)	48.0	Yes	Ram	Slope (%)	5.0
No	Ramp Width (in)	34.5	Yes	Ramp	xSlope (%)	1.3
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To SE		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.8		X Wa	ılk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	1.8		X Wa	ılk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	p inside XWalk2?	N/A
	Road Slope (%)	1.8	N/A	Clear	Space?	N/A
	Road X Slope (%)	1.8	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ice Condition? (G/P)	Good