

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|   |  |   |
|---|--|---|
| Intersection ID: 3448                   | Main Street: W W T HARRIS BV TO I-77 RA SB | Location: SE                            |
| ADA ID: 08312A7C9969                    | Ramp Type: Para                            | Initial Pass/Fail: Fail                 |
|   | Overall Compliance: No                     | Severity Score: 26.25                   |
| Codes/Mitigation Info/Possible Solution |  | Field Measurements/Component Compliance |



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**RT RP < 5%**

PROW/ADA:

**R304.3.2, R304.5.3**

Total Cost: \$ 1600.00

| Compliance | Description          | Data  | Compliance | Description                 | Data |
|------------|----------------------|-------|------------|-----------------------------|------|
| N/A        | Ramp Length LT (in)  | 64.0  | N/A        | Ramp Length RT (in)         | 46.5 |
| Yes        | Ramp Width LT (in)   | 68.0  | Yes        | Ramp Width RT (in)          | 68.0 |
| No         | Ramp Slope LT (%)    | 16.2  | Yes        | Ramp Slope RT (%)           | 0.0  |
| No         | Ramp XSlope LT (%)   | 2.1   | Yes        | Ramp XSlope RT (%)          | 0.5  |
| N/A        | Landing Length (in)  | N/A   | N/A        | DWS Provided?               | N/A  |
| N/A        | Landing Width (in)   | N/A   | N/A        | DWS Contrast?               | N/A  |
| N/A        | Landing Slope (%)    | N/A   | N/A        | DWS Length (in)             | N/A  |
| N/A        | Landing X Slope (%)  | N/A   | N/A        | DWS Full Width?             | N/A  |
| N/A        | Landing Curb? (Y/N)  | N/A   | N/A        | DWS Offset (in)             | N/A  |
| N/A        | Shared Landing?      | N/A   |            |                             |      |
| N/A        | Gutter Ponding?      | N/A   | N/A        | Gutter Slope (%)            | N/A  |
| N/A        | Gutter Lip Ht (in)   | N/A   | N/A        | Gutter X Slope (%)          | N/A  |
| N/A        | Painted X Walk1?     | Yes   | N/A        | Painted X Walk2?            | N/A  |
|            | X Walk 1 Direction   | To N  |            | X Walk 2 Direction          | N/A  |
| N/A        | X Walk 1 Width (in)  | 107.0 | N/A        | X Walk 2 Width (in)         | N/A  |
|            | X Walk 1 Slope (%)   | 5.2   |            | X Walk 2 Slope (%)          | N/A  |
|            | X Walk 1 X Slope (%) | 5.2   |            | X Walk 2 X Slope (%)        | N/A  |
| N/A        | Ramp inside XWalk1?  | Yes   | N/A        | Ramp inside XWalk2?         | N/A  |
|            | Road Slope (%)       | N/A   | N/A        | Clear Space?                | N/A  |
|            | Road X Slope (%)     | N/A   | N/A        | Clear Space to XWalk (in)   | N/A  |
| N/A        | Any Obstructions?    | N/A   | N/A        | Storm Grate/Utility Hazard? | N/A  |
|            | Obstruction Type     |       |            | Storm Grate/Utility Type    |      |
|            |                      | N/A   |            |                             | N/A  |
|            |                      |       | Yes        | Surface Condition? (G/P)    | Good |
|            |                      |       | N/A        | Curb Slope (%)              | 9.2  |

