


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8350	Main Street: LASALLE_ST	Cross Street: CUSTER_ST	Location: NW
ADA ID: 0848E7208064	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 22.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		Compliance	Description	Data
	Surveyor Notes:		No	Ramp Length (in)	59.5
	N/A		No	Ramp Width (in)	40.0
	PROW/ADA:		N/A	Flare Type LT	N/A
	Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	N/A
			To SE	X Walk 1 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A
			0.1	X Walk 1 Slope (%)	N/A
			3.9	X Walk 1 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Road Slope (%)	N/A
			N/A	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
			N/A	Obstruction Type	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 1850.00

