

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49195	Main St	Cross Street: DERITA_WOODS_CT					Location:	NW	
ADA ID: 085A91D75AEC	Ramp T	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
DERILA TROODS GT CA		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.1
		Two New Directional Ramps or	••••	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		3		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
EAN 1				N/A	Shared Landing?	N/A		,	
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Stand Fail		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
And An	1 MAT	Not i ound, K304.3.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
ALL AND	3			X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	DERITA WOODS CT	-			X Walk 1 Slope (%)	5.4		X Walk 2 Slope (%)	1.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.9		X Walk 2 X Slope (%)	4.1
Street 2 Name	GRAYPARK DR			N/A	Ramp inside XWalk1?	2.0 N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			N/A	Road Slope (%)	4.0	N/A	Clear Space?	N/A
	None				Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	2.3 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00	N/A	Obstruction Type			Storm Grate/Utility Type	1975
						N/A		eterm erate/etanty type	N/A
						11/1	1		10/5

s Surface Condition? (G/P)

Good

