cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29731 Main Street: RUSHMORE_DR Cro				HARNEY DR	Location:	NE			
ADA ID: 086631D88367 Ramp Type: PerpDiag								50.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	<u>C</u>	Compliance Description		Data Compliance Description		Data		
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	ith N/	Α	Ramp Length (in)	79.0	No	Ramp Slope (%)	13.6	
		No	0	Ramp Width (in)	41.0	No	Ramp XSlope (%)	9.9	
		N/.	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		N/	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	<i>I</i>	N/	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/	Α	Shared Landing?	N/A				
	PROW/ADA:	N/	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	R304.5.1, R304.2.2, R304.5.3	N/	Α	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	·····,····,····,·····,·····	N/	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
		N/	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name RUSHMORE DF				X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	0.3	
Stop Condition-Street 2 None	1			X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	3.6	
Street 2 Name HARNEY DF		N/	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopSigr				Road Slope (%)	7.4	N/A	Clear Space?	N/A	
				Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A	
		N/	/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

s Surface Condition? (G/P)

Good

