cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025303	Main Street: E_4TH_ST		Cross	Cross Street: N/A				Location:	W
ADA ID: 088AAC173332	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	42.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
The second s	1 10 2	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	75.0	No	Ramp Slope (%)	9.5
		Two New Directional Ramps or		No	Ramp Width (in)	34.0	No	Ramp XSlope (%)	6.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Ba				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1 A A A A A A A A A A A A A A A A A A A				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
1777 5.				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		-		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
BI AND BEE		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
States 188		Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	1.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	1.4
Street 2 Name	E 4TH ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.9	N/A	Clear Space?	N/A
					Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

