cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24803 Main Street: CHOATE CR Cross Street: HARLEQUIN E								Location:	NE
	Main Street: CHOATE_CR								
ADA ID: 0895973401E8	Ramp Type: PerpDiag		Initial P	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	6.4
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.9
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
to the second se		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A STROME				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A Contraction				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
THE REAL PROPERTY OF THE PARTY	1			N/A	Shared Landing?	N/A			
the the second sec	The Contraction	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	The second second	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	V. Barnet			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HARLEQUIN DR				X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	2.5
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	1.4
Street 2 Name	CHOATE CR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.6	N/A	Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

