

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25795 Main Street: PINEVILLE-MATTHEWS_RD Cross Street: CARY_RIDGE_DR Location: S

ADA ID: 08CCE614E328 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 35

Codes/Mitigation Info/Possible Solution



Street 1 Name
CARY RIDGE DR
Stop Condition-Street 2
StopSign
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	ı
	I
	ı
	l
Surveyor Notes:	
N/A	ı
	ı
	ı
	ı
PROW/ADA:	l
Not Found, R304.5.1, R304.2.2, R304.5.3	1
	I

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Compl	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	14.0	
No	Ramp Width (in)	44.0	No	Ramp XSlope (%)	2.4	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





