

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



					. /					
Intersection ID: 48198	ersection ID: 48198 Main Street: RIVERGATE_PY			Cros	Cross Street: S_TRYON_ST				Location:	SW
ADA ID: 0929BA825E13	Ramp Ty	Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Complian			o Severity Score:	21.25
Cod	es/Mitigation Info/	Possible Soluti	on			Field Measur	ements/C	ompo	nent Compliance	
KING HOLE		Possible Solutions:			Compliance Description		Data Compliance Description		Data	
5. S. S.		Remove & Re	place Entire Ra	amp.	N/A	Ramp Length LT (in)	50.0	N/A	Ramp Length RT (in)	60.0
					Yes	Ramp Width LT (in)	72.0	Yes	Ramp Width RT (in)	72.0
the and					Yes	Ramp Slope LT (%)	5.6	Yes	Ramp Slope RT (%)	5.8
TRECOUL	de la				Yes	Ramp XSlope LT (%)	1.4	No	Ramp XSlope RT (%)	2.7
a a a a a a a a a a a a a a a a a a a					N/A	Ramp Length (in)	97.0	Yes	Ramp Slope (%)	6.5
0	A ALIA				No	Ramp Width (in)	44.0	No	Ramp XSlope (%)	6.8
1000	alto la	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
CO BE		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	ALC I				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
12 m M	1 1 1 2 1				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	13 11 5	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	A: 1 .	Not Found, R	304.5.1, R304.	5.3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	real to		·		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1. M. 1. 1. 1.				N/A	Shared Landing?	N/A			
	A STAN				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	<b>RIVERGARE PY</b>				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	112.0		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
								N/A	Any Obstruction?	N/A
		AL		Marshalk Marshalk Marshalk Marshalk Tri MAR Tri MAR Tri Mars					Obstruction Type	N/A

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	18.9



