

# Access Compliance Report

## Public Rights-of-Way (Curb Ramps)

Intersection ID: 9996	Main Street: BARRINGTON_DR	Cross Street: WOODY_GLEN_PL	Location: SW
ADA ID: 09321E110C44	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 25	

### Codes/Mitigation Info/Possible Solution

### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.2.2-Perp, R304.3.2-Para, R304.5.2, R305, R302.7.2**

Total Cost: \$ 1600.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	100.0	No	Grade Break?	No
Yes	Ramp Width (in)	60.5	N/A	Grade Break Slope (%)	N/A
Yes	Ramp Slope (%)	5.4	N/A	Grade Break XSlope (%)	N/A
Yes	Ramp XSlope (%)	0.9			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Yes	Flare Slope LT (%)	2.7	N/A	Flare Slope RT (%)	3.5
N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	50.5	No	DWS Provided?	No
Yes	Landing Width (in)	53.0	N/A	DWS Contrast?	No
No	Landing Slope (%)	2.9	N/A	DWS Length (in)	N/A
Yes	Landing X Slope (%)	0.7	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
N/A	Shared Landing?	No	N/A	DWS Offset RT (in)	N/A
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.9
No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	0.1
N/A	Painted X Walk1?	No		Road Slope (%)	4.1
	X Walk 1 Direction	To NW		Road X Slope (%)	5.6
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	5.6	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	10.9

Street 1 Name	WOODY GLEN PL
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

