cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28141	Cross	ross Street: OLD_ARDREY_KELL_RD				Location:	SE	
	Main Street: PROVIDENCE_RD_WEST							
ADA ID: 095C375B45BD Ramp Type: PerpDiag		Initial P	nitial Pass/Fail: Fail Overall Compliance: No				Severity Score:	21.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description D			ta Compliance Description		Data
And a state of the	Remove & Replace Curb Ramp	o With	N/A	Ramp Length (in)	93.0	No	Ramp Slope (%)	8.6
	Two New Directional Ramps of	r	No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.6
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A WEST			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PROVIDENCE RD WEST	and the second se		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	and the second sec		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2	2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To N		X Walk 2 Direction	To SW
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name PROVIDENCI	E RD WEST			X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	0.9
Stop Condition-Street 2	None			X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	2.5
Street 2 Name OLD ARDRE	EY KELL RD		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign			Road Slope (%)	1.1	N/A	Clear Space?	N/A
				Road X Slope (%)	3.2	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

es Surface Condition? (G/P)

Good

