


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 46739	Main Street: BOBHOUSE_DR	Cross Street: BEAVER_BROOK_WY	Location: SE
ADA ID: 096C2D5DBF37	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 10	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
 <p>Street 1 Name BOBHOUSE DR</p> <p>Stop Condition-Street 2 None</p> <p>Street 2 Name BEAVER BROOK WY</p> <p>Stop Condition-Street 1 StopSign</p>	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		Yes	Ramp Slope (%)	7.9
			No	Ramp Width (in)	3.2
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Landing Length (in)	N/A
			N/A	Landing Width (in)	N/A
			N/A	Landing Slope (%)	N/A
			N/A	Landing X Slope (%)	N/A
			N/A	Landing Curb? (Y/N)	N/A
			N/A	Shared Landing?	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter Lip Ht (in)	N/A
			No	Painted X Walk1?	No
			To N	X Walk 2 Direction	To W
			N/A	X Walk 1 Width (in)	N/A
			1.1	X Walk 1 Slope (%)	4.6
			3.7	X Walk 1 X Slope (%)	2.1
			N/A	Ramp inside XWalk1?	N/A
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.5.1, R304.5.3</p> <p>Total Cost: \$ 3200.00</p>			N/A	Ramp inside XWalk2?	N/A
			3.4	Road Slope (%)	N/A
			3.3	Road X Slope (%)	N/A
			N/A	Any Obstructions?	N/A
				Obstruction Type	
			N/A	Storm Grate/Utility Hazard?	N/A
				Storm Grate/Utility Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

