## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



			-						
Intersection ID: 14426	Main Str	Cross Street: RANIER_AV					Location:	W	
ADA ID: 096E8795BAE4	Ramp Ty	Ramp Type: Perp			il: Fail Overall C	o Severity Score:	13.75		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
State and the state of the	- 1 200 C	Possible Solutions:	Compliance Description			Data	Data Compliance Description		Data
	1 and the	Remove & Replace Entire Ramp		I/A	Ramp Length (in)	154.0	No	Ramp Slope (%)	8.7
A A A A A A A A A A A A A A A A A A A			١	'es	Ramp Width (in)	119.0	Yes	Ramp XSlope (%)	2.1
			Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Ser		Ν	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
B I	ALASS A		N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Man 6	A		Ν	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
BINGTICK &	Not a state of the	Surveyor Notes:	Ν	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
L Contraction	10 m	N/A	Ν	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
a la tradition			N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Corres-		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A DA	100		N	I/A	Shared Landing?	N/A			
Kor Kor	las a	PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
a lesta	She was	R304.2.2	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
1000 000000			N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	ST A				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
Service A 198			N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name W	EDDINGTON AV	_			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			١	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good





