

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30556	Main Str	Main Street: GREEN_LEA_CT			Street:	GREENCREEK_DR	Location:	SW		
ADA ID: 09B2E5E9D5D9	Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	15.25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	14	Possible Solutions:			Compliance Description			Data Compliance Description		
and the second		Remove & Replace Entit	Entire Ram	p.	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.5
		Remove & Replace			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.2
					N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
A LAND	110.2003				N/A	Flare Slope LT (%)	5.5	Yes	Flare Slope RT (%)	5.5
					N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
A Starter Star					No	Landing Length (in)	47.0	No	DWS Provided?	No
E M	n	Surveyor Notes:			Yes	Landing Width (in)	48.0	N/A	DWS Contrast?	No
		N/A			No	Landing Slope (%)	2.3	N/A	DWS Length (in)	N/A
					Yes	Landing X Slope (%)	1.2	N/A	DWS Full Width?	No
				N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	No				
	PROW/ADA:			Yes	Gutter Ponding?	No	No	Gutter Slope (%)	6.5	
	R304.5.3, R304.2.1, R304.2.2-Perp,			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.1	
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	R304.3.2-Para, R305		• *	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	GREENCREEK DR					X Walk 1 Slope (%)	3.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	Yes
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$	2600.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

