

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32185 Main Street: CAMELLIA_LN				Cross	Street:	REA_RD	Location:	NE		
ADA ID: 09D4D1F56E				Initial Pass/Fail: Fail Overall Compliance: No					13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:						Compliance Description Data		
Contraction of the second		Remove & Replace E	Entire Ramp	_	N/A	Ramp Length (in)	93.0		Ramp Slope (%)	8.9
1 1 2 2 2 3	Monthly				Yes	Ramp Width (in)	65.0	No	Ramp XSlope (%)	2.3
	and success of	3			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
11.11.2	Cars. C	<u>8</u>			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1 11 11					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	NETS DES	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	the state Phile	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	NENGAL				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Rea				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A I WILL					N/A	Shared Landing?	N/A			
	C CART D	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1 II Fre	Not Found, R304.2.2	. R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
ALLA BUR S	1111 Jan ~~		,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
CAMP-	111111					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
<u>A</u>	a 11 11				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	REAVENCREST PARK DR	_				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	7.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

