

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10033470 Main Street: OLD\_PINEVILLE\_RD Cross Street: N/A Location: E

ADA ID: 0A17AE6F15B9 Ramp Type: Perp Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 0

Ramp Type: Perp Initial Pass/Fail: Pass Overall Compliance: No Severall Compliance: No Severall Compliance: No Severall Component Compliance:

## Codes/Mitigation Info/F

| Street 1 Name           | OLD PINEVILLE RD |
|-------------------------|------------------|
| Stop Condition-Street 2 | None             |
| Street 2 Name           | N/A              |
| Stop Condition-Street 1 | N/A              |

| /Possible Solution            |  |  |  |  |  |
|-------------------------------|--|--|--|--|--|
| Possible Solutions:           |  |  |  |  |  |
| Remove & Replace Entire Ramp. |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
| Surveyor Notes:               |  |  |  |  |  |
| N/A                           |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
| PROW/ADA:                     |  |  |  |  |  |
| Not Found, R305.1.4           |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |
|                               |  |  |  |  |  |

|  |  | - |
|--|--|---|
|  |  |   |
|  |  |   |
|  |  |   |

Total Cost:



1850.00

| Field Measurements/Component Compliance |                       |        |      |                             |      |  |  |
|-----------------------------------------|-----------------------|--------|------|-----------------------------|------|--|--|
| Comp                                    | liance Description    | Data   | Comp | liance Description          | Data |  |  |
| N/A                                     | Ramp Length (in)      | 47.0   | Yes  | Ramp Slope (%)              | 6.9  |  |  |
| Yes                                     | Ramp Width (in)       | 48.0   | Yes  | Ramp XSlope (%)             | 0.0  |  |  |
| N/A                                     | Flare Type LT         | Sloped | N/A  | Flare Type RT               | N/A  |  |  |
| N/A                                     | Flare Slope LT (%)    | 0.8    | Yes  | Flare Slope RT (%)          | 0.7  |  |  |
| N/A                                     | Flare Traversable LT? | Yes    | N/A  | Flare Traversable RT?       | Yes  |  |  |
| Yes                                     | Landing Length (in)   | 79.0   | Yes  | DWS Provided?               | Yes  |  |  |
| Yes                                     | Landing Width (in)    | 48.0   | Yes  | DWS Contrast?               | Yes  |  |  |
| Yes                                     | Landing Slope (%)     | 1.2    | No   | DWS Length (in)             | 23.5 |  |  |
| Yes                                     | Landing X Slope (%)   | 0.2    | Yes  | DWS Full Width?             | Yes  |  |  |
| N/A                                     | Landing Curb? (Y/N)   | No     | Yes  | DWS Offset (in)             | 0.0  |  |  |
| N/A                                     | Shared Landing?       | No     |      |                             |      |  |  |
| Yes                                     | Gutter Ponding?       | No     | Yes  | Gutter Slope (%)            | 4.1  |  |  |
| Yes                                     | Gutter Lip Ht (in)    | 0.0    | Yes  | Gutter X Slope (%)          | 0.4  |  |  |
| N/A                                     | Painted X Walk1?      | No     | N/A  | Painted X Walk2?            | N/A  |  |  |
|                                         | X Walk 1 Direction    | To W   |      | X Walk 2 Direction          | N/A  |  |  |
| N/A                                     | X Walk 1 Width (in)   | N/A    | N/A  | X Walk 2 Width (in)         | N/A  |  |  |
|                                         | X Walk 1 Slope (%)    | 2.3    |      | X Walk 2 Slope (%)          | N/A  |  |  |
|                                         | X Walk 1 X Slope (%)  | 0.5    |      | X Walk 2 X Slope (%)        | N/A  |  |  |
| N/A                                     | Ramp inside XWalk1?   | N/A    | N/A  | Ramp inside XWalk2?         | N/A  |  |  |
|                                         | Road Slope (%)        | N/A    | N/A  | Clear Space?                | Yes  |  |  |
|                                         | Road X Slope (%)      | N/A    | N/A  | Clear Space to XWalk (in)   | N/A  |  |  |
| Yes                                     | Any Obstructions?     | No     | Yes  | Storm Grate/Utility Hazard? | No   |  |  |
|                                         | Obstruction Type      |        |      | Storm Grate/Utility Type    |      |  |  |
|                                         |                       | N/A    |      |                             | N/A  |  |  |
|                                         |                       |        | Yes  | Surface Condition? (G/P)    | Good |  |  |