

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



	Mata Of		0	- <b>4</b> - 19 -				Lander	0.44
Intersection ID: 3691	ntersection ID: 3691 Main Street: DEER_CROSS_TL		Cross Street: IVY_BROOK_CT				Location:	SW	
ADA ID: 0A5D2310B8F3 Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	<u>Co</u>	mpliar	nce Description	Data	Comp	liance Description	Data
	1	Remove & Replace Entire Ramp	N/4	<b>A</b> F	Ramp Length (in)	42.0	N/A	Grade Break?	N/A
			No	F	Ramp Width (in)	40.0	N/A	Grade Break Slope (%)	0.0
			Yes	s F	Ramp Slope (%)	7.5	N/A	Grade Break XSlope (%)	0.0
	×/		Yes	s F	Ramp XSlope (%)	0.2			
A CONTRACT OF CONTRACT.			N/#	<b>A</b> F	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/#	<b>1</b> F	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:	N/#	A F	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
L C.		N/A	N/#	<b>\</b> L	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
			N/A	<b>\</b> L	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
			N/A	<b>\</b> L	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
			N/A	<b>\</b> L	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:	N/A	<b>\</b> L	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.1	N/A	A S	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
			N/A	<b>A</b> (	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N/A	<b>A</b> (	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			N/A	A P	Painted X Walk1?	No		Road Slope (%)	0.7
Street 1 Name	VY BROOK CT			Х	X Walk 1 Direction	To NE		Road X Slope (%)	2.9
Stop Condition-Street 1	StopSign			Х	X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A			Х	X Walk 1 Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A			Х	X Walk 1 X Slope (%)	2.9	N/A	Storm Grate/Utility Hazard?	N/A
			N/#	A F	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			N/#	<b>a</b> A	Any Obstructions?	N/A			N/A
		Total Cost: \$ 1	600.00	C	Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	9.0

