

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A		Main Street: PENCE_RD		Cross Street: HICKORY_TRACE_DR		Location: NW							
ADA ID: 0A6DF61E475D		Ramp Type: Directional1		Initial Pass/Fail: Pass		Overall Compliance: No		Severity Score: 0.25					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance									
<div></div> <div>Possible Solutions:</div> <div>Remove & Replace Landing.</div> <div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>R304.2.2-Perp, R304.3.2-Para</div>				Compliance	Description	Data	Compliance	Description	Data				
				N/A	Ramp Length (in)	117.0	Yes	Grade Break?	Yes				
				Yes	Ramp Width (in)	52.0	Yes	Grade Break Slope (%)	1.9				
				Yes	Ramp Slope (%)	3.3	Yes	Grade Break XSlope (%)	2.4				
				Yes	Ramp XSlope (%)	3.6							
				Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A				
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No				
				Yes	Landing Length (in)	54.0	Yes	DWS Provided?	Yes				
				Yes	Landing Width (in)	55.0	Yes	DWS Contrast?	Yes				
				No	Landing Slope (%)	4.1	Yes	DWS Length (in)	24.0				
				Yes	Landing X Slope (%)	2.6	Yes	DWS Full Width?	Yes				
				N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	1.0				
				N/A	Shared Landing?	No	Yes	DWS Offset RT (in)	1.0				
				Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.8				
				Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	3.7				
				N/A	Painted X Walk1?	No		Road Slope (%)	2.1				
					X Walk 1 Direction	To E		Road X Slope (%)	3.8				
					X Walk 1 Width (in)	N/A		Clear Space?	Yes				
					X Walk 1 Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A				
					X Walk 1 X Slope (%)	3.8	Yes	Storm Grate/Utility Hazard?	No				
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type					
				Yes	Any Obstructions?	No			N/A				
					Obstruction Type		Yes	Surface Condition? (G/P)	Good				
							N/A	Curb Slope (%)	6.5				
				Total Cost:		\$	500.00						

