

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

12.2

2.3

N/A

N/A

N/A

Intersection ID: 17310 Main Street: QUEENS RD WEST **Cross Street: SELWYN AV** Location: NW

ADA ID: 0AE7A00F9972 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 26.25

Flare Traversable LT?

Codes/Mitigation Info/Possible Solution

Total Cost:

Field Measurements/Component Compliance

48.0 No

N/A N/A

No

N/A

N/A

Data

63.0

N/A

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Flare Type RT



	THE RESIDENCE OF THE PERSON NAMED IN
Street 1 Name	SELWYN AV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Compliance Description
Remove & Replace Entire Ramp.	N/A Ramp Length (in)
·	Yes Ramp Width (in)
	N/A Flare Type LT
	N/A Flare Slope LT (%)
	N/A Flare Traversable L
	N/A Landing Length (in)
Surveyor Notes:	N/A Landing Width (in)
N/A	N/A Landing Slope (%)
	N/A Landing X Slope (%
	N/A Landing Curb? (Y/N
	N/A Shared Landing?
PROW/ADA:	N/A Gutter Ponding?
Not Found, R304.2.2, R304.5.3	N/A Gutter Lip Ht (in)
,	N/A Painted X Walk1?
	X Walk 1 Direction
	N/A X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (
	N/A Ramp inside XWalk
	Road Slope (%)
	5 13/61 (0/)

	· . • • • • • • • • • • • • • • • • • •		



1850.00

N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	То Е		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	5.4		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
W 200 N					