


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A	Main Street: CHARLOTTE_PARK_DR	Cross Street: N/A	Location: SW
ADA ID: 0B447DAEE31F	Ramp Type: PerpDiag	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 20	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent. Gutter Ponding Observed.</b>		N/A	Ramp Length (in)	116.5	Yes	Ramp Slope (%)	5.8
			Yes	Ramp Width (in)	65.0	Yes	Ramp XSlope (%)	0.5
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	7.4	N/A	Flare Slope RT (%)	9.9
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			No	Landing Length (in)	N/A	No	DWS Provided?	No
			No	Landing Width (in)	N/A	N/A	DWS Contrast?	No
			No	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			No	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, R302.7</b></p>			N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	No			
			No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	2.4
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.2
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To E		X Walk 2 Direction	To N
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	5.2
				X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	1.8
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	0.8	N/A	Clear Space?	Yes	
			Road X Slope (%)	4.9	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
			Obstruction Type			Storm Grate/Utility Type		
					N/A		N/A	
						Yes	Surface Condition? (G/P)	Good
Total Cost:		\$ 3700.00						

