

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19799 Main Street: SHARON_RD Cross Street: COLONY_RD Location: N

ADA ID: 0B788D703E5B Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

COLONY RD
Stop Condition-Street 2

Signal
Street 2 Name

Stop Condition-Street 1

Signal

Total Cost: \$ 3400.00

Field Measurements/Component Compilance						
Compliance Description		Data	Data Compliance Description		Data	
N/A	Ramp Length (in)	26.0	No	Ramp Slope (%)	8.6	
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.7	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes	
	X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	108.0	
	X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	3.7	
	X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	4.4	
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	No	
	Road Slope (%)	1.5	N/A	Clear Space?	N/A	
	Road X Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





