

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 1361	A Main Str	eet: OLD_STEELE_CREEK_RD	Cross	Street:	WESTHAMPTON_DR			Location:	NE
ADA ID: 0B9687A089				itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
Possible Solutions:				Comp	liance Description	Data Compliance Description			Data
京和訪察! / .	A A A	Remove & Replace Curb Ramp	A/ith	N/A	Ramp Length (in)	44.0	Yes	Ramp Slope (%)	<u>5.9</u>
MATON IN	* 1 1 1 1	Two New Directional Ramps or	vvitri	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.5 7.1
	A Part	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	P P			N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
	149			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	March 116			N/A	Landing Length (in)	N/A		DWS Provided?	N/A
	TONDER	Surveyor Notes:		N/A	Landing Width (in)	N/A		DWS Contrast?	N/A
	t TIESTIANIPTONE	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		2110 011001 ()	
where and had		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
	Not i ouna, N304.3.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	1-36 195				X Walk 1 Direction	To W		X Walk 2 Direction	To S
	11, 200 11			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	OLD STEELE CREEK RD				X Walk 1 Slope (%)	9.7		X Walk 2 Slope (%)	1.6
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	6.2
Street 2 Name	WESTHAMPTON DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	3.9	N/A	Clear Space?	N/A
					Road X Slope (%)	8.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A		5 51	N/A
							Yes	Surface Condition? (G/P)	Good

