

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

Intersection ID: 10033044 Main Street: NOLLEY\_CT Cross Street: N/A Location: **Overall Compliance: No ADA ID: 0B9A1EB6F57E** Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Severity Score: 21.25

Compliance Description

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

Data Compliance Description



**Remove & Replace Curb Ramp With** Two New Directional Ramps or Equivalent.

Surveyor Notes: N/A

| Street 1 Name           | NOLLEY CT |
|-------------------------|-----------|
| Stop Condition-Street 1 | None      |
| Street 2 Name           | N/A       |
| Stop Condition-Street 2 | N/A       |
|                         |           |
|                         |           |

|                    |               | N/A |
|--------------------|---------------|-----|
|                    |               | N/A |
| PROW/ADA:          |               | N/A |
| R304.5.1, R304.5.3 |               | N/A |
|                    |               | N/A |
|                    |               |     |
|                    |               | N/A |
|                    |               | N/A |
| Total Cost:        | \$<br>3200.00 |     |
|                    |               |     |



| N/A               | Ramp Length (in)      | 95.0  | Yes | BlendTrans Slope (%)        | 2.6  |
|-------------------|-----------------------|-------|-----|-----------------------------|------|
| No                | Ramp Width (in)       | 45.0  | No  | BlendTrans XSlope (%)       | 5.7  |
| N/A               | Flare Type LT         | N/A   | N/A | Flare Type RT               | N/A  |
| N/A               | Flare Slope LT (%)    | N/A   | N/A | Flare Slope RT (%)          | N/A  |
| N/A               | Flare Traversable LT? | N/A   | N/A | Flare Traversable RT?       | N/A  |
| N/A               | Landing Length (in)   | N/A   | N/A | DWS Provided?               | N/A  |
| N/A               | Landing Width (in)    | N/A   | N/A | DWS Contrast?               | N/A  |
| N/A               | Landing Slope (%)     | N/A   | N/A | DWS Length (in)             | N/A  |
| N/A               | Landing X Slope (%)   | N/A   | N/A | DWS Full Width?             | N/A  |
| N/A               | Landing Curb? (Y/N)   | N/A   | N/A | DWS Offset (in)             | N/A  |
| N/A               | Shared Landing?       | N/A   |     |                             |      |
| N/A               | Gutter Ponding?       | N/A   | N/A | Gutter Slope (%)            | N/A  |
| N/A               | Gutter Lip Ht (in)    | N/A   | N/A | Gutter X Slope (%)          | N/A  |
| N/A               | Painted X Walk1?      | No    | N/A | Painted X Walk2?            | N/A  |
|                   | X Walk 1 Direction    | To SE |     | X Walk 2 Direction          | N/A  |
|                   | X Walk 1 Width (in)   | N/A   |     | X Walk 2 Width (in)         | N/A  |
|                   | X Walk 1 Slope (%)    | 0.1   |     | X Walk 2 Slope (%)          | N/A  |
|                   | X Walk 1 X Slope (%)  | 4.4   |     | X Walk 2 X Slope (%)        | N/A  |
| N/A               | Ramp inside XWalk1?   | N/A   | N/A | Ramp inside XWalk2?         | N/A  |
|                   | Road Slope (%)        | 4.4   |     | Clear Space?                | N/A  |
|                   | Road X Slope (%)      | 0.1   | N/A | Clear Space to XWalk (in)   | N/A  |
| N/A               | Any Obstructions?     | N/A   | N/A | Storm Grate/Utility Hazard? | N/A  |
|                   | Obstruction Type      |       | l   | Storm Grate/Utility Type    |      |
|                   |                       | N/A   | l   |                             | N/A  |
|                   |                       |       | Yes | Surface Condition? (G/P)    | Good |
|                   | <b>第一个</b>            |       | N/A | Curb Slope (%)              | 0.4  |
| The second second |                       |       |     |                             |      |



