

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17049Main Street: HANSON\_DRCross Street: HAMPTON\_AVLocation: NWADA ID: 0BC133BB433ERamp Type: Directional1Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 35

## Codes/Mitigation Info/Possible Solution



Street 1 Name HANSON DR
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solutions:	Co			
Remove & Replace Entire Ramp.				
	No			
	No			
	No			
	N/			
	N/			
Surveyor Notes:	N/			
N/A	N/			
	N/			
	N/			
	N/			
PROW/ADA:	N/			
R304.5.1, R304.2.2, R304.5.3	N/			





Total Cost:



1600.00

Field Measurements/Component Compliance						
Compliance Description Data		Comp	liance Description	Data		
N/A	Ramp Length (in)	53.5	N/A	Grade Break?	N/A	
No	Ramp Width (in)	44.0	N/A	Grade Break Slope (%)	0.0	
No	Ramp Slope (%)	13.3	N/A	Grade Break XSlope (%)	0.0	
No	Ramp XSlope (%)	3.6				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No		Road Slope (%)	2.7	
	X Walk 1 Direction	To S		Road X Slope (%)	0.8	
	X Walk 1 Width (in)	N/A		Clear Space?	N/A	
	X Walk 1 Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A	
	X Walk 1 X Slope (%)	0.8	N/A	Storm Grate/Utility Hazard?	N/A	
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
N/A	Any Obstructions?	N/A			N/A	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
		N/A	N/A	Curb Slope (%)	1.6	