cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



			`									
Intersection ID: N/A	Main Str	eet: PENCE_GROVE_R	D	Cross	Street:	PENCE_RD			Location:	NE		
ADA ID: 0C06AB7D9053	Ramp Ty	Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian			ice: No Severity Score: (0		
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description				
	States.	Remove & Replace C	urb Ram	np With	N/A	Ramp Length LT (in)	47.0	N/A	Ramp Length RT (in)	57.0		
R R		Two New Directional Ramps or Equivalent.			Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.0		
				Yes	Ramp Slope LT (%)	4.6	No	Ramp Slope RT (%)	9.3			
				No	Ramp XSlope LT (%)	2.4	No	Ramp XSlope RT (%)	2.9			
					N/A	Ramp Length (in)	50.0	Yes	Ramp Slope (%)	5.1		
					No	Ramp Width (in)	33.0	Yes	Ramp XSlope (%)	0.2		
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
G. PENOS	20				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
6.					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
SP STORES	and the second s	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
1 101238		R304.5.1, R304.5.3, R	304.3.2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
The Product of	A 19 4 4				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	Title Carlos Stra				N/A	Shared Landing?	N/A					
Martin Part and a state of the second state of	E del 12- 1	4			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
Stop Condition-Street 1	PENCE GROVE RD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
Street 2 Name	None					X Walk 1 Direction	To W		X Walk 2 Direction	To S		
Stop Condition-Street 2	PENCE RD					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
						X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	0.9		
						X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	3.3		
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
						Road Slope (%)	0.1		Clear Space?	N/A		
						Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A		
				A 19	the second	SI 4 40 -		N/A	Any Obstruction?	N/A		
	States and a states	and the second second		272					Obstruction Type			
PENDE		Market Contraction			The state of the s					N/A		
					07			N/A	Storm Grate/Utility Hazard?	N/A		
	Television	1	-						Storm Grate/Utility Type	174		
		1 in			1-					N/A		

		N/A
Yes	Surface Condition? (G/P)	Good
	Curb Slope (%)	N/A





