

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/AMain Street:BERE_ISLAND_DRCross Street: N/ALocation:NWADA ID: 0C41B1C21801Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 2

Street 2 Name

N/A

Stop Condition-Street 1

N/A

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 1850.00

Field Measurements/Component Compliance						
Comp	iance Description	Data	Compl	iance Description	n	Data
N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)		7.6
No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	ı	2.3
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%	(a)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable	RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?		N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?		N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)		N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?		N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)		N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)		N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%	o)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?		N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	า	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (ir	۱)	N/A
	X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%	6)	N/A
	X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope	(%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWa	lk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?		N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XV	Valk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility	/ Hazard?	N/A
	Obstruction Type			Storm Grate/Utility	/ Туре	
		N/A				N/A
			Yes	Surface Condition	? (G/P)	Good
	4					





