

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		`			<u> </u>						
Intersection ID: 24374 Main Street: BEVERLY_CREST_BV					Cross Street: HUGH_FOREST_RD				Location:	NE	
ADA ID: 0CF9C6E6AE	D: 0CF9C6E6AE04 Ramp Type: Combination1				Initial Pass/Fail: Fail Overall Compliance				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
Possible Solutions:					Compliance Description			Data Compliance Description			
	ALL LING	Remove & Replace Ent	ire Rar	mp.	N/A	Ramp Length LT (in)	32.0	N/A	Ramp Length RT (in)	20.0	
	Mr. AN S//				Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0	
<u>6</u>	oma a l				Yes	Ramp Slope LT (%)	5.8	Yes	Ramp Slope RT (%)	6.2	
A MARIA					Yes	Ramp XSlope LT (%)	1.4	No	Ramp XSlope RT (%)	3.1	
Ha I III					N/A	Ramp Length (in)	94.0	No	Ramp Slope (%)	9.5	
	- / @/				Yes	Ramp Width (in)	60.0	No	Ramp XSlope (%)	5.9	
	ALE A	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
- PA	the state	CURB LIP 2.0			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	alistic all				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	Call Call				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
Xa Xa		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	A	R304.2.2, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	Part - Carlos - Carlos	,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	12 House				N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	PINEVILLE-MATTHEWS RD				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	102.0		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			200			N/A	Any Obstruction?	N/A	
	DE 1 Ales					and the second			Obstruction Type		
				in the state						N/A	
								N/A	Storm Grate/Utility Hazard?	N/A	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 1.7





