

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | | |
|------------------------|-------------------------|-------------------------|------------------------|----------------------|
| Intersection ID: 13982 | Main Street: CLEMENT_AV | Cross Street: PARK_DR | Location: | E |
| ADA ID: 0D18114FEE31 | Ramp Type: Perp | Initial Pass/Fail: Pass | Overall Compliance: No | Severity Score: 22.5 |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Detectable Warning System. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

R305.1.4, R302.7, R302.7.2, R304.5.4

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|--------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 82.0 | Yes | Ramp Slope (%) | 5.2 |
| Yes | Ramp Width (in) | 74.0 | Yes | Ramp XSlope (%) | 1.6 |
| N/A | Flare Type LT | Sloped | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | 11.0 | N/A | Flare Slope RT (%) | 16.3 |
| N/A | Flare Traversable LT? | No | N/A | Flare Traversable RT? | No |
| Yes | Landing Length (in) | 84.0 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 74.0 | Yes | DWS Contrast? | Yes |
| Yes | Landing Slope (%) | 1.6 | Yes | DWS Length (in) | 24.0 |
| Yes | Landing X Slope (%) | 0.5 | No | DWS Full Width? | No |
| N/A | Landing Curb? (Y/N) | No | Yes | DWS Offset (in) | 2.0 |
| N/A | Shared Landing? | No | | | |
| No | Gutter Ponding? | Yes | No | Gutter Slope (%) | 5.7 |
| No | Gutter Lip Ht (in) | 1.0 | Yes | Gutter X Slope (%) | 1.4 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 4.7 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 0.5 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | Yes |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |

Total Cost: \$ 1550.00

