## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10029240 Main Street: JOHNSTON RD Cross Street: N/A								L C	05
Intersection ID: 10029240	ersection ID: 10029240 Main Street: JOHNSTON_RD			Street:	N/A	Location:	SE		
ADA ID: 0D25EA36F35F	DA ID: 0D25EA36F35F Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	18.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Curb Ramp	Nith	N/A	Ramp Length (in)	120.0	Yes	Ramp Slope (%)	6.1
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	35.0	No	Ramp XSlope (%)	2.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	E TO			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	THE A			N/A	Shared Landing?	N/A			
PROW/ADA: Not Found, R304.5.1, R304.		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found. R304.5.1. R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE	_			X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	0.3
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	0.4
Street 2 Name J	OHNSTON RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.3	N/A	Clear Space?	N/A
					Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P) Good

