

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

N/A

N/A

N/A

N/A

8.0

3.3

N/A

Main Street: SCALEYBARK RD Intersection ID: 17008 Cross Street: UNIVERSITY DR Location: **Overall Compliance: No** ADA ID: 0D341BF9497D Ramp Type: Combination2 Initial Pass/Fail: Fail Severity Score: 13.75

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

52.0

70.0

9.2

4.0

71.0

59.0

N/A

No

N/A

5.2

To SW

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name None Stop Condition-Street 1 **SCALEYBARK RD** N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes No No N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.3, R304.3.2 N/A N/A N/A N/A N/A N/A





Total Cost:



		X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A
1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	N/A		Clear Space?	N/A
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstruction?	N/A
	Road X Slope (%)  N/A  N/A  Clear Space to XWalk (in)  N/A  N/A  Obstruction?  Obstruction Type  N/A  N/A  Storm Grate/Utility Hazard?  Storm Grate/Utility Type					
						N/A
				N/A	Storm Grate/Utility Hazard?	N/A
					Storm Grate/Utility Type	
					N/A	
		:\		Yes	Surface Condition? (G/P)	Good
					Curb Slope (%)	21.9